

Solving environment-related business problems worldwide

www.deltaenv.com

27141 Aliso Creek Road • Suite 270 Aliso Viejo, California 92656 USA 949.362.3077 800.477.7411 Fax 949.362.0290 October 13, 2005

Mr. Sam Stevens Los Angeles County Department of Public Works 900 South Fremont Avenue Alhambra, California 91803

Sent by UPS

Subject:

Quarterly Update Report Submittal

Dear Mr. Stevens:

On behalf of Atlantic Richfield Company, Delta Environmental Consultants, Inc. is submitting the enclosed Quarterly Site Status Report for the Third Quarter 2005. The enclosed quarterly report was prepared for the following ARCO Facility:

ARCO Facility No.

LADPW Site No.

Location

1592

EP-1 011979-037116

5 West Foothill Blvd, Arcadia

If you have any questions, please contact the undersigned at (949) 360-5789.

Sincerely,

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Amy R. Mora Project Manager

Enclosure:

Atlantic Richfield Company Quarterly Site Status Report

cc:

Mr. Bobby Lu, Atlantic Richfield Company, La Palma, California Mr. John Nahas, 5 West Foothill Boulevard, Arcadia, California

ATLANTIC RICHFIELD COMPANY QUARTERLY SITE STATUS REPORT **THIRD QUARTER 2005 OCTOBER 15, 2005**

ARCO Facility No.: 1592

Address:

5 West Foothill Boulevard, Arcadia, California

Atlantic Richfield Co. Env. Manager / Phone No.:

Mr. Bobby Lu / (714) 228-6783

Consulting Co. / Contact Person / Phone No.:

Delta Environmental / Ms. Amy Mora / (949) 360-5789

Primary Agency / Contact Person / Regulatory ID No.: County of Los Angeles Department of Public works (LADPW) /

Mr. Sam Stevens / EP-1 011979-037116

WORK PERFORMED THIS QUARTER (Third - 2005):

1. Submitted the second quarter 2005 Quarterly Site Status Report to the LADPW.

WORK PROPOSED FOR THE NEXT QUARTER (Fourth - 2005):

1. Submit Quarterly Site Status Report.

Current Phase of Project:

Assessment/Closure

Depth to Groundwater:

200+ feet Measured Estimated X

Groundwater Gradient:

Unknown (Magnitude) Unknown (Direction)

ATTACHMENTS:

Site Location Map (Figure 1)

Site Map (Figure 2)

DISCUSSION:


The hydrocarbon-impacted soil at the site has been sufficiently assessed vertically and horizontally. Therefore, on behalf of Atlantic Richfield Company, Delta requests that no further actions be required of Atlantic Richfield Company for this site.

If you have any questions or comments concerning this correspondence, please contact Amy Mora at (949) 360-5789.

DELTA ENVIRONMENTAL CONSULTANTS, INC.

Amy Mora

Project Manager



GENERAL NOTES:
BASE MAP FROM 3-D TOPO QUADS
MT. WILSON, CA. QUADRANGLE
7.5 MINUTE TOPOGRAPHIC MAP
1966
PHOTOREVISED 1988







FIGURE 1


* SITE LOCATION MAP ARCO FACILITY NO. 1592 5 W. FOOTHILL BOULEVARD ARCADIA, CA.

PROJECT NO.		DRAWN BY	
AM03-169			
FILE NO.		PREPARED BY	
A3-808-03		A. BAIRD	
DATE	REV.	REVIEWED BY	
09 DEC 03	0		





FOOTHILL BLVD



LEGEND

8-1 SOIL VAPOR EXTRACTION WELL LOCATION

B-2 • SOIL BORING LOCATION

T5A ▼ TANK SOIL SAMPLE LOCATION

D4A ▼ DISPENSER SOIL SAMPLE LOCATION

APPROXIMATE LIMIT OF OVEREXCAVATION

FIGURE 2

SITE MAP
ARCO FACILITY NO. 1592
5 WEST FOOTHILL BOULEVARD
ARCADIA, CA.

PROJECT NO.		DRAWN BY	
AM03-169		K. MARTIN	
FILE NO.		PREPARED BY	
A3-169-01		A. BAIRD	
DATE		REVIEWED BY	
17 MAR 04	0		

